RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11158

RECEIVED FROM PLANT #9

DATE REC'D 2-4-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	000000	10130	0	0	00	00			

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
24	[illegible]-5 Gear Assy-Center Mags. Drive	24	✓	
	To supersede Rec. Insp. Report #11129			
	INTERPLANT SHIP TR #2837			STAT [redacted]

STAT
STAT
RECEIVED BY [redacted]

INSPECTED BY [redacted]

DATE 2/4/57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1069

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11172

RECEIVED FROM PLANT #9

DATE REC'D 2-5-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	000000	10030	0	0	00	00			

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
125	737434 Washer Hammer Latch	125	✓	
	Shipper 28915			STAT [redacted]

STAT
STAT
RECEIVED BY [redacted]

INSPECTED BY [redacted]

DATE 2/5/57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1069